# STENOS TRACK FIELD CUTTING INSTRUCTIONS

**PLEASE READ ALL INSTRUCTIONS PRIOR TO INSTALLATION AND KEEP FOR FUTURE REFERENCE!**

luminii


REV0.2
03252026

1 / 1


7777 MERRIMAC AVE
NILES, IL 60714
T 224.333.6033
F 224.757.7557
INFO@LUMINII.COM
WWW.LUMINII.COM

## Field Cutting (All Tracks: STS, STH, STT, STL, and STD Models)


**1**





**1.1** Pull out the insulator/spacer from the end of the extrusion to be cut.




**1.2** When cutting the extrusion in field, ensure that the extrusion is sitting perpendicular to the cutting surface.





**1.3** Trim the power track back 5/8" with hand shears to fit the length of the extrusion,so that there is enough room for the end insulator/spacer to be installed.



**1.4** Re-install insulator/spacer onto cut end.

## Continuous Row Mounting (Only Necessary for STS Surface Track and STT Trimmed Recessed Track)

**2**




**2.4** For continuous row mounting, the straight mechanical joiner uses the same channel that the power track resides in. The power track needs to be cut back 1-1/4" from the end where the mechanical joiner will be inserted.

*LUMINII RESERVES THE RIGHTS TO CHANGE SPECIFICATION & INSTRUCTION WITHOUT NOTICE